

Date: Tuesday, 1/15/2008 1:27:00 PM
 User: David Duval

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D3552-7
Job Number	: 36776		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D35527
This Issue	: 1/15/2008 S.O. No. :	Drawing Number	: RTN671
Prsht Rev.	: NC	Project Number	:
First Issue	: 1/1	Drawing Revision	:
Previous Run	: 00015	Material	:
Written By	: <i>[Signature]</i> 08-01-15	Due Date	: 1/22/2008 Qty: 1 Um: Each
Checked & Approved By	:		
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description:
---------	-----------------------	--------------

1.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

2.0	D35527	CARBON STEEL GAS SPRING
-----	--------	-------------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)
 CARBON STEEL GAS SPRING
 qty 1 original batch B30638

3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------



Comment: SMALL & MEDIUM FAB RESOURCE 1
 SCrap and destroy. Qty 1 B30638, D3552-7

4.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion

